San	tized Cor	y Approve	ed for Rele	ase 201	0/08/16 :	CIA-R	DP80T00246A	.05120052000	1-5
•	,	¥					1	x. 11	
U		., <u>C</u>	けって	A Section (Section)	1	77			

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

			S-E-C-R-E-T	!			50X1-HUM
COUNTRY	East Germany	-		REPORT			
SUBJECT	Soviet Tank Re	pair Shop Wue Tanks under	nsdorf: Repair	DATE DISTR.	\$2 0CT	1959	
				NO. PAGES	1		
				REFERENCES	RD		
DATE OF INFO.							50X1-HUM
PLACE & DATE ACC				PRAISAL OF CONT			50X1-HUM
		m- 1 D 1 -	0	۰۰- د داد هم د		report	
	on the Soviet on the followi		Shop in Wuens	dorf which co	ntains i	nformation	
						5074 111	
						50X1-HU	IM
				.02		•	
. #				of glacis and tank fitting		les.	
		entified turre		Commission of the commission o			
May.	Included is a			ring:			
	a. Glacis and	l nose plate a	ngles				
	b. Auxiliary	fuel tank fit	tings				
	c. Unidentifi	ed turret fit	t i ngs				50X1-HUM
							(D)
							(V)
							\
			S-E-C-R-E-1	r			
STATE	ARMY #X	IAVY			OF	R x	
	ington distribution indicated						.,

Sanitized Copy Approved for Release 2010/08/16 : CIA-RDP80T00246A051200520001-5

50X1-HUM

Sanitized Copy Approved for Release 2010/08/16 : CIA-RDP80T00246A051200520001-5

	Sanitized Copy Approved for Release 2010/08/16 : CIA-RDP8	30T00246A051200520001-5	
•	SECRET		50X1-HUM
			I

25 August 1959

EAST GERMANY/U.S.S.R.

MILITARY

Miscellaneous Information regarding T54 and PT 76
Tanks undergoing repair at the Soviet A.F.V. Repair
Workshops at WUNSDORF

(August 1959)

50X1-HUM

T 54 Dimensions relevant to ascertaining the angle of the glacis and nose plates.

2. A T54 hull undergoing repair in the workshops was mounted so that its belly plate was 63 cms. from the floor. When so mounted the junction of the glacis plate and lower nose plate was 96 cms. from the floor. The glacis plate was 132 cms. in length, and the lower nose plate 68 cms. (See also Appendix "A" Fig. 1).

T54 Trials with new auxiliary fuel tank fittings.

- 3. In mid-August 1959 trials were currently in progress testing out a fitting at the rear of a T54, to which 4 auxiliary fuel tanks were attached; a side view of this is shown in fig. 2 at Appendix "A". Four auxiliary tanks were carried horizontally on a framework which appeared to be collapsible, or at least capable of folding when not in use. The fuel tanks were each approximately 50 cm. in diameter and their length was equal to the width of the tank hull. They were connected to each other, and the top one to a fitting on the hull, by flexible piping.
- 4. The capacity of each auxiliary fuel tank is 150 litres.

/page 2...

Sanitized Copy Approved for Release 2010/08/16: CIA-RDP80T00246A051200520001-5

SECRET

50X1-HUM

- 2 -

T54:

Turret Fittings

50X1-HUM

5. A T54 tank which had been fully repaired and reassembled during July/August 1959 had two fittings on the turret which have not been fitted to the turrets of other T54s which have to date passed through these workshops. Sketches of these fittings are shown in Appendix "A", fig. 3. The smaller fitting was attached to a bracket just in front of the left hatchway in the top of the turret, while the larger fitting was attached to a bracket immediately to the right of the gun mantlet. The front of each fitting was protected by a removable metal covering plate. No cables or other electrical leads were visible in connection with either of these fittings.

SECRET

985

50X1-HUM

APPENDIX "A"






Fig 2



F16.3



Diameter - approx 20 ems Length - " 30 ems.



Diameter - approx 25-30 cm hangth - " 16 cms

50X1-HUM

APPENDIX "A"






FIG 2



F16.3



Diameter - approx 20 cms. Longth - " 30 cms



Diameter - approx 25-30 em